

# Error memory

Date: 2/28/26, 3:29 PM

VIN: 5UXCR6C55KLL11680

## 12 Digital Motor Electronics

### 6 errors

CD990B: FlexRay, message (request rear axle speed, 69.3.4): missing

CD990E: FlexRay, message (request front axle speed, 69.3.4): missing

CDA713: FA-CAN, message (flashing, 0x1F6): missing

180001: Catalytic converter: efficiency below limit value

216115: Pinion starter: An attempt to start with a blocked starter detected

1F0549: Check control message (ID 2064): engine oil service required

## 29 Dynamic stability control

### 6 errors

480AE4: Interface QDM - actual steering angle front axle - signal implausible

480907: Interface QDM - Ackermann target yaw rate - signal invalid

48069E: RDCi calibration wheel detection not possible

4806F0: RDCi wheel electronics rear left no reception

48077C: RDCi wheel electronics front left Battery undervoltage

48077D: RDCi wheel electronics front right Battery undervoltage

## 2C PMA

### 4 errors

803207: Sensor technology: noise detected

80334C: Multi-turn loss detected

D42DA1: Signal error (odometry vehicle 1, ID: ODO\_VEH\_1) - Invalid

D42DA9: Signal error (is vector vehicle movement, ID: AVL\_VEC\_VHMOV) - Invalid

## 30 Electromechanical power steering

### 1 error

D51408: Signal (vehicle speed, ID: V\_VEH) invalid

## 39 Virtual integration system

### 4 errors

D7553D: Signal (status stabilization DSC, ID: ST\_STAB\_DSC) invalid

D75511: Signal (status ECBA, ID: ST\_ECBA) invalid

D7556D: Signal (target haptic warning of leaving lane, ID: TAR\_FEEL\_WARN\_LNDP) invalid

03054A: QDM-SBS - Steering angle effective model error

## 40 Body Domain Controller

### 5 errors

804081: Production readiness to drive: faulty

804082: Requirement for engine running as a stationary function: faulty

8040C6: KL30F: Reset request due to closed-circuit current violation

8040D2: PWF status activation: Parking BN not ok

804136: CKT: Disabled

## 5D Camera-based driver assist system

### 8 errors

E05620: 0xE05620 - signal error - 0x3538 - 0x0001 - BMW.DASS - DriverAssistanceComfortAndSecurity - signal invalid

E0561A: 0xE0561A - signal error - 0x7532 - 0x0001 - BMW.CHASSIS - SteeringAngle - signal invalid

800ABF: KAFAS camera: field of view temporarily disturbed

E0561B: 0xE0561B - signal error - 0x7530 - 0x0001 - BMW.CHASSIS - VehicleModel - signal invalid

E05614: 0xE05614 - signal error - 0x7531 - 0x0001 - BMW.CHASSIS - DrivingVector - signal invalid

800AC5: KAFAS window heating: Short circuit to positive or interruption

800A24: Temporary software error

800ABE: KAFAS camera: Field of view permanently disturbed

## 61 Telematic Communication Box

### 1 error

031786: SIF: Last State Call

## 63 Headunit High

### 7 errors

031798: SIF: BT Audio Browsing

031791: SIF: connection BT

E1C600: Ethernet: physical error (link off)

B7F89E: Security: Secure Time Backend certificate invalid

031799: SIF: connection app

03179A: SIF: CarPlay connection

031793: SIF: connection WLAN

## 76 Vertical dynamics platform

### 1 error

E6959C: Signal error (target proportion of steering control, ID: TAR\_QTA\_CTR\_STE)  
- Invalid