

Error memory

Date: 3/9/21, 9:26 AM
VIN: 5YMCY0C09M9F14913

01 Airbag

1 error

C95461: Speed: communication failure

04 Rear electric ARS

1 error

48362F: Power supply - degradation under or over voltage external

29 Dynamic stability control MK60 E5

3 errors

D35DCE: Signal (component of roll torque stabilization SP2015, ID: QTA_MX_STAB_SP2015) invalid

D354BE: Signal (vehicle speed, ID: V_VEH) invalid

D356E4: Message (status distribution longitudinal torque front axle rear axle, ID: ST_REPAT_XTRQ_FTAX_BAX) is missing

2C Parking maneuvering assistant

3 errors

80334A: RFA function aborted due to incorrect operation

D42DA1: Signal error (odometry vehicle 1, ID: ODO_VEH_1) - Invalid

D42DA9: Signal error (is vector vehicle movement, ID: AVL_VEC_VHMOV) - Invalid

30 Electric steering lock

1 error

D51408: Signal (vehicle speed, ID: V_VEH) invalid

39 Vertical dynamics management

5 errors

D754CD: Unknown error

D75529: Unknown error

D75601: Unknown error

D7556D: Unknown error

D7552E: Unknown error

5D Camera-based driver assist system

5 errors

E05620: 0xE05620 - signal error - 0x3538 - 0x0001 - BMW.DASS - DriverAssistanceComfortAndSecurity - signal invalid

E0561B: 0xE0561B - signal error - 0x7530 - 0x0001 - BMW.CHASSIS - VehicleModel - signal invalid

E05614: 0xE05614 - signal error - 0x7531 - 0x0001 - BMW.CHASSIS - DrivingVector - signal invalid

E05618: 0xE05618 - Signal error - 0x7533 - 0x0001 - BMW.CHASSIS - SpeedAcceleration - signal invalid

800ABF: KAFAS camera: field of view temporarily disturbed

76 Vertical dynamics management

1 error

E694BE: Signal error (vehicle speed, ID: V_VEH) - Invalid