

Programming: Changes with 25-03 I level update that are perceptible to the customer 83598.1

Here you can find changes in the vehicle that are noticeable by the customer, which are included in an I level update 25-03.



The functions in this document apply to all vehicles from Service Pack 2021 and Service Pack 21R.


1. Personal eSIM

Relevant for markets: Germany, Austria, Switzerland, France, Netherlands, Belgium, Luxembourg, Spain, Portugal, Italy, UK, USA, Japan, Korea

Affected vehicles: BMW: G45, U11, U06, F70, F74, U11, U10; MINI: U25, J01, F65, F66, F67, J05

Optional equipment required: SA-6PA

BMW: Personal eSIM expanded to include Wi-Fi hotspot and improved telephony: With this update, you can quickly set up a Wi-Fi hotspot in your BMW that uses the vehicle's powerful external aerials. Optimised reception improves the data connection. This enables you to make particularly good quality phone calls on the road.





2. Lock/unlock

Relevant for markets: All BMW ConnectedDrive markets

Affected vehicles: All vehicles with Headunit High 4, Headunit High 5 and Headunit High 6

Optional equipment required: SA-322

BMW: Unlocking and locking now also via the My BMW App: From now on, you can also unlock and lock your BMW using the My BMW App. This works from a distance of only a few metres and even if your smartphone does not have an Internet connection. Using the BMW Digital Key Plus is the prerequisite.

MINI: Unlocking and locking now also via the MINI App: From now on, you can also unlock and lock your MINI using the MINI App. This works from a distance of only a few metres and even if your smartphone does not have an Internet connection. Using the MINI Digital Key Plus is the prerequisite.



3. Partial arming of alarm system

Relevant for markets: All BMW ConnectedDrive markets

Affected vehicles: All vehicles with Service Pack 2021

Optional equipment required: SA-322, SA-302, SA-6AE (without SA-8TV)

BMW: Reduced alarm function can now also be set via smartphone: After this update, you can control the motion and inclination sensors by means of the My BMW App when you are near the vehicle. As soon as these alarm functions are disabled, any false alarm caused by any movement or vibration is prevented. This is a useful option when you park your BMW in a duplex garage or on a swaying ferry. Using the BMW Digital Key Plus is the prerequisite.

MINI: Reduced alarm function can now also be set via smartphone: After this update, you can control the motion and tilt sensors by means of the MINI App when you are near the vehicle. As soon as these alarm functions are disabled, any false alarm caused by any movement or vibration is prevented. This is a useful option when you park your MINI in a duplex garage or on a swaying ferry. Using the MINI Digital Key Plus is the prerequisite.

BMW:



MINI:



4. Open/close boot

Relevant for markets: All BMW ConnectedDrive markets

Affected vehicles: All vehicles with Service Pack 2021 and Service Pack 2021R

Optional equipment required: SA-322 (without SA-8TV), SA-6AE, SA-316

BMW: The tailgate can now also be operated via smartphone: With this update, you can now also open the tailgate via the My BMW App when you are near your BMW. You can find this option under "Remote Controls". If you keep the button pressed, the tailgate will close again. Provided your BMW is equipped with automatic tailgate operation and you are using the BMW Digital Key Plus.

MINI: The tailgate can now also be operated via smartphone: With this update, you can now also open the tailgate via the MINI App when you are near your MINI. You can find this option under "Remote Controls". If you keep the button pressed, the tailgate will close again. Provided your MINI is equipped with automatic tailgate operation and you are using the MINI Digital Key Plus.

BMW:



MINI:



5. MyMode efficient startup mode

Relevant for markets: All ConnectedDrive markets (excluding: USA, Canada, Korea, Brazil, India)

Affected vehicles: BMW: All vehicles with Service Pack 21 (BEV) with Headunit High 5 and Headunit High 6

Special equipment required: SA-802, SA-8LB, SA-8LA

BMW: My Mode EFFICIENT now as start mode: With this update, you no longer have to manually switch to My Mode EFFICIENT after setting off. On request, your BMW automatically starts and drives in the most efficient mode.

MINI: Your MINI now drives in green mode right from the start: With this update, you no longer need to manually switch to Green Mode after starting to drive. On request, your MINI will automatically start and drive in the most efficient mode.

BMW:



MINI:



6. Home address exception


Relevant for markets: All BMW ConnectedDrive markets

Affected vehicles: BMW: All vehicles with Service Pack 2021 with Headunit High 5

Optional equipment required: -

BMW: Comfort Access can now be adjusted for the home address: This upgrade allows you to adjust the Comfort Access feature for your home address. In the Comfort Access menu, you can set your home address as an

exception to disable automatic unlocking when passing by your BMW. This ensures your vehicle remains locked when approaching until manually accessed.




7. Exception logic of heat management

Relevant for markets: All BMW ConnectedDrive markets

Affected vehicles: BMW: All vehicles (BEV only) with Service Pack 2018 and 2021 (OS8, OS8.5, OS9)

Optional equipment required: -

BMW: Expanded battery heat management display: With this update, the “Prepare battery” icon appears not only when outside temperatures are cold, but also when they are warm. You are therefore always informed when the battery in your BMW has reached the ideal charging temperature. The icon is visible as soon as you have started driving on the route to a quick charging station and as long as battery heat management for optimized DC charging is active.



8. IPA Speech Alexa

Relevant for markets: USA

Affected vehicles: BMW: G45, F70, F74

Optional equipment required: -

BMW: Your BMW now understands more with Amazon Alexa: Your BMW can now process multiple voice commands when you connect your Amazon account. With “Hey BMW”, it thus also reacts to commands that were previously only possible using Alexa. The new function is initially available for music search and streaming. The scope is constantly being expanded.

MINI: Your MINI now understands more with Amazon Alexa: Your MINI can now process multiple voice commands when you connect your Amazon account. With “Hey MINI”, it thus also reacts to commands that were previously only possible using Alexa. The new function is initially available for music search and streaming. The scope is constantly being expanded.

BMW:



MINI:



9. IPA Avatar Hong Kong

Relevant for markets: Hong Kong

Affected vehicles: MINI: All vehicles with Headunit High 6

Optional equipment required: -

MINI: New Avatar “Spike” for your MINI Intelligent Personal Assistant: Spike is available from now on as an additional avatar for your MINI Intelligent Personal Assistant. This allows you to choose between visualisation of a MINI or Spike. To do this, open the app settings of the MINI Intelligent Personal Assistant and select your preferred animation.



10. Plug and Charge PHEV

Relevant for markets: Germany, Austria, Switzerland, France, Netherlands, Belgium, Luxembourg, Spain, Portugal, Italy, Nordics, UK, EU Mediterranean, Central Europe, Baltic States, USA, Canada, Korea

Affected vehicles: BMW: All vehicles with Service Pack 21: U06, U11, G60, G61, G70, G90, G99, G05, G09, G45 (PHEVs)

Optional equipment required: -

BMW: Charging with Plug & Charge soon also without app and charging card: This update prepares your BMW for the Plug & Charge function that you will soon be able to use. In future, your vehicle will automatically authenticate itself when you connect the charging cable. You do not require an app or charging card any more. Invoicing at the end of the charging process also takes place automatically. The availability of the service depends on the charging post provider.



11. Navigation user interface/user experience

Relevant for markets: All BMW ConnectedDrive markets

Affected vehicles: BMW: All Service Pack 2021 and Service Pack 21R vehicles with Headunit High 5

Optional equipment required: -

BMW: Faster starting of route guidance with navigation: Additional icons on the search bar in the BMW map view now make it easier to select the destination. With one click, you can select your workplace and home directly or remove stored destinations using the X button. You can use the new flag button in the search results to start route guidance immediately. In addition, the most important functions are now opened when you open the map for the first time.



12. Quality measure for climate comfort

Relevant for markets: USA, Brazil, Korea, China

Affected vehicles: BMW: G07 LCI (from build level >= 08/22)

Optional equipment required: SA-4NN

BMW: Faster heating and higher heater output in your BMW: Climate control performance is improved with this update. The interior of your BMW now heats up even faster in cold temperatures. In addition, the heater output is increased.



13. Quality measure Remote Engine Start

Relevant for markets: USA

Affected vehicles: **BMW:** G07 LCI (from build level >= 08/22)

Optional equipment required: SA-1CR

BMW: Remote Engine Start now functions even more reliably. This update improves the Remote Engine Start function. The connection is more stable. Your BMW engine starts more reliably from a distance when you activate the function using the My BMW App or vehicle key.



14. Head Unit optimisation

Relevant for markets: All BMW ConnectedDrive markets

Affected vehicles: **BMW:** F70, F74, U06, U10, U11, U12 (only vehicles with Headunit High 6); **MINI:** F65, F66, F67, J01, J05, U25

Optional equipment required: -

BMW: Control display with optimised performance: The overall performance, especially in the entertainment and control display area, will improve after this update. Several features and functions are now even more stable. The performance of your BMW system is thus improved and the user experience is visibly increased.



15. Quality measure IPA Speech

Relevant for markets: UK, Ireland, Canada, USA, Mexico, France, Germany, Spain, Italy, Luxembourg, Liechtenstein, Portugal, China, Austria, Iceland, Malta

Affected vehicles: BMW: G45, F70, F74; MINI: U25, J01, J05, F6x

Optional equipment required: -

BMW: Improved speech recognition and function for your voice assistant: Voice control access to contacts in the selected phone book in the telephone app is now automatic - manual selection no longer necessary. Problems with the detection of the "Drive me home" or "Drive me to work" commands have been solved. The search for and detection of radio stations by your voice assistant has been improved.

MINI: Improved speech recognition and function for your voice assistant: Voice control access to contacts in the selected phone book in the telephone app is now automatic - manual selection no longer necessary. Problems with the detection of the "Drive me home" or "Drive me to work" commands have been solved. The search for and detection of radio stations by your voice assistant has been improved.



Target groups :

Independent Operator
Internal Location
Retailer Organisation

3/3/25, 9:46 AM

Programming: Changes with 25-03 I level update that are perceptible to the customer

Branch : Car
Topic : Vehicle Programming
Sub-Group-1 : #SW#ISTA
Sub-Group-2 : BUSINESS-OP
Translate this document within
the next 5 minutes : No