

Service Information Bulletin

Fuel Supply Systems

November 5, 2020

B16 04 20

DELIVERY STOP: TANK VENTILATION DIAGNOSIS

MODEL

E-Series	Model Description	Production Date
F90	M5 Sedan	April 16, 2018 – November 4, 2020
F91	M8 Convertible	October 16, 2018 - June 29, 2020
F92	M8 Coupe	October 15, 2018 – June 26, 2020
F93	M8 Gran Coupe	June 19, 2019 – November 3, 2020
F95	X5 M Sports Activity Vehicle	April 20, 2018 – November 4, 2020
F96	X6 M Sports Activity Coupe	March 25, 2019 – November 3, 2020
F97	X3 M Sports Activity Vehicle	October 2, 2019 – August 11, 2020

AFFECTED VEHICLES

Vehicles which require this Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System), ISPA Next or Warranty Vehicle Inquiry.

SITUATION

BMW AG has issued a Delivery Stop (effective November 5, 2020) on certain Model Year 2019-2021 BMW vehicles that were produced between April 16, 2018 and November 4, 2020.

There may be a malfunction in the diagnosis of the tank ventilation. As a result, the customer would not be notified of an emissions-related error.

Do not deliver to a customer, a New, Certified Pre-Owned or Used vehicle subject to a Delivery Stop, until the vehicle is repaired. Do not use or sell replacement equipment/parts subject to a Delivery Stop.

The bulletin will be updated when additional information becomes available.